


Fracture



- Fig. 1. Adequate support for Catamaran using a fitted cradle.
- Fig. 2. A trailer with rollers only will result in fractures at the turn of the bilge.
- Fig. 3. Typical support for Pintail, Copperhead, or Sidewinder other round hulls.
- Fig. 4. Suitable support for Copperhead and Sidewinder placing longitudinal support at the vertical inner cockpit wall.
- Fig. 5. Most boat trailers with longitudinal supports are too wide. This arrangement will result in fractures as indicated (as will rolling the boat on it's side if full of water).